

S0#			
-----	--	--	--

Other units:

CTDI Poland.

Logistyczna 7

Poland

05090 Sekocin Stary

Attn.: Motorola Solutions Repair

RMA FORM

- 1. Fields marked with * are mandatory
- Please read Terms & Conditions (on the bottom of this form)
- For infrastructure and outside EU repair email the form to repair.emea@motorolasolutions.com
- 4. Customer Care will create the RMA number for you and update the form
- 5. Please print this form and attach to your shipment

Customer number * 1036524107 RMA# (infrastructure, outside-EU)

21 €	
Customer P0 number	*
Customer reference	

Email: repair.emea@motorolasolutions.com Tel: +44 207 019 0461 / 0800 731 3496

Encrypted units, ASTRO/LEX11/

Attn.: Motorola Solutions Repair

MXP600 devices:

Erfurter Höhe 10a

99610 Sömmerda

Germany

Unit and Fault description

CTDI Germany

RETURN ADDRESS DETAILS

CUSTOMER INFORMATION

Return company name * Datamatik AS Return full address * Jerikoveien 16 (Street No., Apt. No., 1067 Oslo, Norway Post Code, City, Country

Contact name (a	ttn.) *	Neda Akhtari	
Email address *	neda	@datamatik.no	
Phone number	+47 2	2 30 17 30	

INVOICE ADDRESS DETAILS

Company name *	Datamatik AS	
Invoice full address (Street No., Apt. No., Post Code, City, Country)	1067 Oslo, Norway	

Contact name *	Neda Akhtari
Email address *	neda@datamatik.no
Phone number	+47 22 30 17 30

SHIPPING INFORMATION

ACCESSORIES Battery

SUPPLIED

Dead

Does not log in

Is the unit shipped in a secure box? YES

UNIT INFORMATION

Serial number *	
Part number / Model *	
Option (Features)	
Software version	
Software upgrade allowed YES	□ NO
Note: For Mototrbo Repair requiring Mainboard r	eplacement, Firmware cannot be
Upgrade to the latest software	Return unrepaired
Is the unit encrypted or controlled? * [YES Type: NO
End user Name and Address * (Only for ATEX, Encrypted and outside EU units)	

Clip

Display – Error

Control Head

Physical damage

Security tag numbers (seals)	
occurry tag numbers (scals)	

ON		
Microphone	Other:	

FAULT INFORMATION* - Please choose at least one option

Antenna

Liquid damage	☐ No / Low transmission
No/ Low Audio	☐ No Squelch
SERVICE* - Please choose one optio	in
Warranty	
Billed repair - with quotation If quote is rejected, a fee will be charged -	60 EUR (or equivalent in your local currency)
Billed repair - no quotation Fixed price from the official price catalogue	will be charged

Description 1	
No Signaling	Chemical damage
No / Low reception	Constant tone
Cannot Read / Program	Battery / Charging Problem

Repair Code:

Scrap per Customer request

Headset

,	
Contract (or Site ID)	Contract No.:
Advance exchange	Contract No.:

TERMS & CONDITIONS:

- A copy of this form (with RMA number whenever applicable) is to be included with defective unit upon ship. Do not send consumable items.—batteries, antennas, cables, SIM/ memory cards unless related to the nature.
- s, cables, SIM/ memory cards unless related to the nature of the fault. Please note that a 60 euro handling fee, or equivalent, might apply if a quotation is not approved within 30 days of being issued,
- rejected, or disputed.

 Handling leas will also be charged for devices shipped to the incorrect repair location. Please be aware that warranty may be void
- if any unauthorised activities are detected.
- If warranty/contract is not confirmed, a quotation will be issued Turn around time will be in accordance with your antitlement.

- If the softwere upgrade is not part of the repair then a charge may be applied.

 Most accessories are non-repairable. Faulty accessories will only be exchanged under warranty. In case warranty expired customer should purchase a new accessory
- Faulty accessories should not be shipped to the Repair Center; exchange should be requested by completing the RMA form and
- emailing it to repair emee@motorofasolutions.com.

 For Mototrbo, customer codeplug could potentially be non compatible with new (higher) FW version. In such case depot will state "Customer codeplug is not compatible with the new version FW, please reprogram the radio" in repair summary and a default codeplug will be loaded.
- For codeplug programming, if chosen by default, any return bounce unit which is related to codeplug, will not be processed as a bounce job
- By submitting repairs that are deemed to be for ATEX/IECEX products, you understand and agree to have the responsibility to ensure the ATEX/IECEX repair certification documents sent out with the repaired radios are sent to the user/owner.